

City of Taunton - Cost Estimation for Parks and Recreation Facilities

City Priorities
Priority 1: Program Access
Priority 2: Safety
Priority 3: Approach and Entrance
Priority 4: Access to Goods and Services
Priority 5: Toilet or Bathing Rooms
Priority 6: Additional Access

*Cost Estimate Notes:
- Cost of design is not included
- Does not include costs when note indicates future work
- Labor cannot be estimated for all remedies
- There is no cost noted when it's presumed to be a maintenance issue.
Estimates are intended as a guide to budgeting access modifications and are not intended to be absolutely comprehensive or definitive.

** 'Dependent on Distance'
Each linear foot of 3 foot wide asphalt costs \$13. Each case requires the City to determine the actual distance to be covered.
The total calculation does not include these costs.

Information Provided by Institute for Human Centered Design										Information Provided by City of Taunton				
FACILITY	REFERENCE #	TO WORK ORDER #	ELEMENT	ISSUE / PHYSICAL BARRIER	LOCATION WITHIN FACILITY	CITY PRIORITIES	PRIORITY FOR BARRIER REMOVAL	ACTION FOR BARRIER REMOVAL	*ESTIMATED COST OF BARRIER REMOVAL	PROJECT START DATE	PROJECT COMPLETION DATE	RESPONSIBLE FOR BARRIER REMOVAL	BARRIER REMOVED	X
Hartshorn Park	287		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided G. Changes in level M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Hopewell Park	410		3. Sidewalk	L. Water accumulation C. Changes in level		Priority 3	Approach & Entrance	Correct change levels at sidewalk.	Dependent on distance	2015	2016	Park and Rec Director	completed	
Hopewell Park	288		1. Walkways	G. Changes in level M. Needs maintenance		Priority 3	Approach & Entrance	Correct change in levels at walkways.	Dependent on distance			Park and Rec Director		
Hopewell Park	305		1. Pedestrian Crosswalk	A. Not Provided at Intersection B. Not Highly Visible C. Uneven, unstable or slippery F. Needs maintenance		Priority 3	Approach & Entrance	Provide marking at crosswalks and repair.	\$1,037.20	2015	2016	Park and Rec Director	completed	
Hopewell Park	306		2. Curb Ramp	B. Not located properly I. Changes in level / sidewalk transitions L. Miss. Flared sides / projects into car path N. Needs maintenance		Priority 3	Approach & Entrance	Repair curb ramps.	\$1,635.00	2015	2016	Park and Rec Director	completed	
Hopewell Park	307		3. Sidewalk	C. Changes in level A. Obstructed		Priority 3	Approach & Entrance	Provide a continuous accessible route.	Dependent on distance	2015	2016	Park and Rec Director	completed	
Hopewell Park	295		1. Drinking Fountains	F. Controls not operable F. Protrusive object		Priority 6	Additional Access	Provide ADA complaint drinking fountains.	\$2,000.00			Park and Rec Director		
Hopewell Park	272		5. Public Toilet Rooms	A. Accessible/unisex not provided B. Not on accessible route		Priority 5	Toilet or Bathing Rooms	Provide ADA complaint public toilet rooms. Cost is for a single user toilet room.	\$11,700.00			Park and Rec Director		
Hopewell Park	293		1. Playground	A. Not connected by accessible route		Priority 1	Program Access	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Hopewell Park	298		2. Water Spray	A. Not connected by accessible route		Priority 1	Program Access	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Hopewell Park	277		2. Field	A. Not connected by accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Hopewell Park	290		2. Field	A. Not connected by accessible route C. Spectator seating not on accessible route E. Team seating not on accessible route F. Practice areas not on accessible route		Priority 1	Program Access	Provide an accessible route to all amenities. Provide one accessible wheelchair space.	Dependent on distance			Park and Rec Director		
Hopewell Park	282		2. Field	C. Spectator seating not on accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Hopewell Park	291		2. Field	E. Team seating not on accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Hopewell Park	411		1. Pedestrian crosswalk	C. Uneven, unstable or slippery		Priority 3	Approach & Entrance	Correct pedestrian crosswalk.	\$1,037.20	2015	2016	Park and Rec Director	completed	
Hopewell Park	280		2. Field	F. Practice areas not on accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Hopewell Park	274		1. Tables	B. At least one or 5% not provided		Priority 4	Access to Goods and Services	Provide one accessible picnic table. Provide an accessible route.	Dependent on distance and furniture selection.			Park and Rec Director		
Hopewell Park	302		3. Benches	C. Adjacent clear space not provided		Priority 4	Access to Goods and Services	Provide an adjacent wheelchair space.	\$52.00			Park and Rec Director		
Hopewell Park	286-287		1. Walkways	C. Route to all features not provided, D. Too narrow, F. Crossslope too steep, H. Obstructed by gates, J. Resting spaces missing or inadequate, M. Needs maintenance, A. Surface uneven, unstable or slippery		Priority 3	Approach & Entrance		Dependent on distance			Park and Rec Director		
Hopewell Park	289		3. Benches	A. Not connected by accessible route		Priority 4	Access to Goods and Services		Dependent on distance			Park and Rec Director		
Hopewell Park	408		1. Pedestrian crosswalk	C. Uneven, unstable or slippery		Priority 3	Approach & Entrance	Correct pedestrian crosswalk.	\$1,037.20	2015	2016	Park and Rec Director	completed	
Hopewell Park	308		3. Sidewalk	C. Changes in level, M. needs maintenance, B. cross-slope too steep		Priority 3	Approach & Entrance	Correct slope and cross slope at sidewalk.	Dependent on distance	2015	2016	Park and Rec Director	completed	
Hopewell Park	407		4. Off-Street Parking Spaces	A. Not connected by accessible route		Priority 3	Approach & Entrance	Provide an accessible route	Dependent on distance			Park and Rec Director		
Hopewell Park	271		6. Gates	Gate smooth surface missing or not compliant, Ground surface uneven, unstable or slippery. Needs Maintenance		Priority 3	Approach & Entrance	Provide smooth surface at gate.	\$400.00			Park and Rec Director		
Boyden Wildlife Sanctuary	002		4. Off-street Parking Space	Access aisle not provided or not compliant Needs maintenance Water accumulation Inadequate # of spaces (quantity) Van-designated space not prov. or not comp. Striping not highly visible Not connected to accessible route		Priority 1	Approach & Entrance	Regrade and restripe parking areas. Provide one van-accessible space. Provide marking at access aisle. Provide parking identification sign.	\$870.00			Park and Rec Director		
Boyden Wildlife Sanctuary	003		4. Off-street Parking Space	Needs maintenance Not connected to accessible route		Priority 1	Approach & Entrance	Provide one accessible route.	Dependent on distance			Park and Rec Director		
Boyden Wildlife Sanctuary	001		5. Point of Entry	A. Not near public transit stop F. Not connected to accessible route H. Needs maintenance		Priority 1	Approach & Entrance	Provide one accessible route.	Dependent on distance			Park and Rec Director		
Boyden Wildlife Sanctuary	011		5. Point of Entry	F. Not connected to accessible route H. Needs maintenance		Priority 1	Approach & Entrance	Provide one accessible route.	\$300.00			Park and Rec Director		
Boyden Wildlife Sanctuary	004		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided G. Changes in level M. Needs maintenance		Priority 1	Approach & Entrance	Correct slope and cross slope at walkways. Provide signs next to accessible routes.	Dependent on distance			Park and Rec Director		
Boyden Wildlife Sanctuary	006		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided G. Changes in level L. Water accumulation M. Needs maintenance		Priority 1	Approach & Entrance	Provide one accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Boyden Wildlife Sanctuary	015		1. Walkways	A. Surface uneven, unstable or slippery M. Needs maintenance		Priority 1	Approach & Entrance	Correct slope and cross slope at walkways.	Dependent on distance			Park and Rec Director		
Boyden Wildlife Sanctuary	005		2. Ramp	A. Surface uneven, unstable or slippery F. Railings missing or not compliant G. Edge protection not provided I. Needs maintenance E. Bottom landing missing or inadequate		Priority 1	Approach & Entrance	Provide an ADA compliant ramp.				Park and Rec Director		
Boyden Wildlife Sanctuary	007 a		5. Public Toilet Rooms	B. Not on accessible route		Priority 5	Toilet or Bathing Rooms	Provide ADA compliant signs.	Dependent on distance			Park and Rec Director		
Boyden Wildlife Sanctuary	007 b		5. Public Toilet Rooms	B. Not on accessible route		Priority 5	Toilet or Bathing Rooms	Provide an ADA compliant ramp.	Dependent on distance			Park and Rec Director		

Boyden Wildlife Sanctuary	008		5. Public Toilet Rooms	B. Not on accessible route		Priority 5	Toilet or Bathing Rooms	Provide one accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Boyden Wildlife Sanctuary	013		1. Tables			Priority 4	Access to Goods and Services	Provide one accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Boyden Wildlife Sanctuary	012		3. Benches	A. Not connected by accessible route B. Ground surface uneven or slippery H. Needs maintenance		Priority 4	Access to Goods and Services	Provide one accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Davol Field	016		3. Sidewalk	M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Davol Field	015		3. Sidewalk	J. Water accumulation A. Obstructed		Priority 3	Approach & Entrance	Repair					Park and Rec Director		
Davol Field	004		4. Off-street Parking Space	Not connected to accessible route		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Davol Field	014		5. Point of Entry	B. Not near off-street parking E. Uneven, unstable or slippery F. Not connected to accessible route H. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Davol Field	006		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Davol Field	007		1. Court	A. Not connected by accessible route B. Spectator seating missing or inadequate D. Team seating missing or inadequate G. Needs maintenance		Priority 1	Program Access	Provide an accessible route. Provide one accessible wheelchair space.	Dependent on distance				Park and Rec Director		
Davol Field	010		2. Field	A. Not connected by accessible route E. Team seating not on accessible route F. Practice areas not on accessible route		Priority 1	Program Access	Provide an accessible route to all amenities. Provide one accessible wheelchair space.	Dependent on distance				Park and Rec Director		
Davol Field	011		2. Field	C. Spectator seating not on accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Davol Field	012		2. Field	E. Team seating not on accessible route A. Not connected by accessible route F. Practice areas not on accessible route		Priority 1	Program Access	Provide an accessible route to all amenities. Provide one accessible wheelchair space.	Dependent on distance				Park and Rec Director		
Hartshorn Park	221		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided M. Needs maintenance	G. Changes in level	Priority 3	Approach & Entrance	Provide an accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Hartshorn Park	405		1. Pedestrian Crosswalk	A. Not Provided at Intersection C. Uneven, unstable or slippery E. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	\$1,037.20				Park and Rec Director		
Hartshorn Park	192		2. Curb Ramp	A. Not provided at Intersection		Priority 3	Approach & Entrance	Provide a curb ramp at intersection.	\$1,635.00				Park and Rec Director		
Hartshorn Park	194		3. Sidewalk			Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	195		3. Sidewalk	B. Cross slope too steep M. Needs maintenance		Priority 3	Approach & Entrance	Correct cross slope.	Dependent on distance				Park and Rec Director		
Hartshorn Park	196		4. Off-street Parking Space	Access aisle not provided or not compliant Ground surface too steep [%] Inadequate # of spaces (quantity) Needs maintenance Not connected to accessible route Sign not provided or not compliant Striping not highly visible Van-designated space not arrow, or not comp.		Priority 3	Approach & Entrance	Provide accessible parking. Provide one van-accessible space. Provide marking at accessible aisle. Provide parking identification sign.	\$870.00				Park and Rec Director		
Hartshorn Park	406		4. Off-street Parking Space	Ground surface too steep [%] Needs maintenance Not connected to accessible route		Priority 3	Approach & Entrance	Provide an accessible route. Correct slope and cross slope at parking area.	Dependent on distance				Park and Rec Director		
Hartshorn Park	203		5. Point of Entry	D. Too narrow E. Uneven, unstable or slippery F. Not connected to accessible route		Priority 3	Approach & Entrance	Correct point of entry width. Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	197		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route		Priority 3	Approach & Entrance	Provide an accessible entrance.	Dependent on distance				Park and Rec Director		
Hartshorn Park	198		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route G. Water accumulation		Priority 3	Approach & Entrance	Provide sign to accessible point of entry.	\$260.00				Park and Rec Director		
Hartshorn Park	200		6. Gates	Gate smooth surface missing or not compliant Ground surface uneven, unstable or slippery Inadequate maneuvering clearances Needs maintenance		Priority 3	Approach & Entrance	Provide a smooth surface at gate.	\$100.00				Park and Rec Director		
Hartshorn Park	199		6. Gates	Ground surface uneven, unstable or slippery Gate smooth surface missing or not compliant		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	202		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	204		1. Walkways	C. Route to all feature not provided A. Surface uneven, unstable or slippery M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Hartshorn Park	220		5. Public Toilet Rooms	B. Not on accessible route		Priority 5	Toilet or Bathing Rooms	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	219		7. Lockers	B. Not on accessible route		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	206		2. Field	A. Not connected by accessible route C. Spectator seating not on accessible route E. Team seating not on accessible route F. Practice areas not on accessible route G. Needs maintenance		Priority 1	Program Access	Provide an accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Hartshorn Park	209		2. Field	A. Not connected by accessible route C. Spectator seating not on accessible route E. Team seating not on accessible route F. Practice areas not on accessible route G. Needs maintenance		Priority 1	Program Access	Provide an accessible route to all amenities.	Dependent on distance				Park and Rec Director		
Hartshorn Park	213		2. Field	F. Practice areas not on accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	208-218 a		1. Tables	C. Not connected by accessible route D. Ground surface uneven or slippery F. Needs maintenance		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Hartshorn Park	208-218 b		1. Tables	A. Total number of tables B. At least one or 5% not provided E. Knee clearance not provided		Priority 4	Access to Goods and Services	Provide one accessible picnic table.	Dependent on distance				Park and Rec Director		
Hartshorn Park	217		2. Services Counters			Priority 4	Access to Goods and Services	Provide one ADA compliant counter.	\$640.00				Park and Rec Director		
Hartshorn Park	216		4. Bleachers	A. Not connected to accessible route B. Ground surface uneven or slippery C. Clear space not provided or not integrated A. Surface uneven, unstable or slippery C. Route to all feature not provided E. Running slope too steep G. Changes in level M. Needs maintenance		Priority 4	Access to Goods and Services	Provide an accessible route. Provide one accessible wheelchair space.	Dependent on distance				Park and Rec Director		
Hartshorn Park	222		1. Walkways			Priority 3	Approach & Entrance		Dependent on distance				Park and Rec Director		
Memorial Park	001		1. Pedestrian Crosswalk	C. Uneven, unstable or slippery E. Needs maintenance		Priority 3	Approach & Entrance		\$1,037.20				Park and Rec Director		
Memorial Park	010		2. Curb Ramp	H. Uneven, unstable or slippery J. Top landing missing or inadequate D. Needs maintenance		Priority 3	Approach & Entrance	Provide a compliant curb ramp.	\$1,635.00				Park and Rec Director		
Memorial Park	011		3. Sidewalk	C. Changes in level M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Memorial Park	004		1. Walkways	A. Surface uneven, unstable or slippery		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance				Park and Rec Director		
Memorial Park	002		1. Walkways	A. Surface uneven, unstable or slippery D. too narrow		Priority 3	Approach & Entrance		Dependent on distance				Park and Rec Director		

Memorial Park	003		1. Walkways	D. too narrow		Priority 3	Approach & Entrance		Dependent on distance			Park and Rec Director		
Memorial Park	006					Priority 6	Additional Access		Dependent on distance			Park and Rec Director		
Sikorski Field	024		5. Point of Entry	A. Not near public transit stop B. Not near off-street parking E. Uneven, unstable or slippery F. Not connected to accessible route H. Needs maintenance G. Water accumulation		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Sikorski Field	013		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route		Priority 3	Approach & Entrance	Provide sign to accessible point of entry.	\$260.00			Park and Rec Director		
Sikorski Field	014		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route		Priority 3	Approach & Entrance	Provide sign to accessible point of entry.	\$260.00			Park and Rec Director		
Sikorski Field	020		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route H. Needs maintenance		Priority 3	Approach & Entrance	Provide sign to accessible point of entry.	\$260.00			Park and Rec Director		
Sikorski Field	019		5. Public Toilet Rooms	B. Not on accessible route A. Accessible/unisex not provided			Other Amenities	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Sikorski Field	022		1. Playground			Priority 1	Program Access					Park and Rec Director		
Sikorski Field	016		1. Playground			Priority 1	Program Access					Park and Rec Director		
Sikorski Field	025		1. Playground			Priority 1	Program Access					Park and Rec Director		
Sikorski Field	011		2. Field	A. Not connected by accessible route C. Spectator seating not on accessible route E. Team seating not on accessible route F. Practice areas not on accessible route G. Needs maintenance		Priority 1	Program Access	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Sikorski Field	026 a		1. Tables	B. At least one or 5% not provided E. Knee clearance not provided F. Needs maintenance		Priority 4	Access to Goods and Services	Provide one accessible picnic table.	Dependent on distance			Park and Rec Director		
Sikorski Field	026 b		1. Tables	C. Not connected by accessible route D. Ground surface uneven or slippery F. Needs maintenance		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Sikorski Field	018		3. Benches	A. Not connected by accessible route B. Ground surface uneven or slippery C. Adjacent clear space not provided H. Needs maintenance		Priority 4	Access to Goods and Services	Provide an accessible route. Provide one accessible wheelchair space.	Dependent on distance			Park and Rec Director		
South St. Playground	028		1. Playground	A. Not connected by accessible route		Priority 3	Approach & Entrance	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
South St. Playground	031		1. Pedestrian Crosswalk	A. Not Provided at Intersection	11	Priority 3	Approach & Entrance	Provide an accessible route.	\$1,037.20			Park and Rec Director		
South St. Playground	030		3. Sidewalk	B. Cross slope too steep	36	Priority 3	Approach & Entrance	Correct slope at cross slope.	Dependent on distance			Park and Rec Director		
Taunton Green	001		1. Pedestrian Crosswalk	C. Uneven, unstable or slippery E. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	\$1,037.20			Park and Rec Director		
Vietnam Fountain	001		3. Sidewalk	B. Cross slope too steep M. Needs maintenance		Priority 3	Approach & Entrance	Correct cross slope.	Dependent on distance			Park and Rec Director		
Vietnam Fountain	005		1. Walkways	A. Surface uneven, unstable or slippery D. too narrow F. Cross slope too steep G. Changes in level M. Needs maintenance		Priority 3	Approach & Entrance	Correct cross slope.	Dependent on distance			Park and Rec Director		
Vietnam Fountain	002		3. Benches	A. Not connected by accessible route		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Park	057		1. Pedestrian Crosswalk	A. Not Provided at Intersection C. Uneven, unstable or slippery		Priority 3	Approach & Entrance	Provide an accessible route.	\$1,037.20			Park and Rec Director		
Weir Park	056		3. Sidewalk	B. Cross slope too steep C. Changes in level		Priority 3	Approach & Entrance	Correct cross slope at sidewalk.	Dependent on distance			Park and Rec Director		
Weir Park	058		4. Off-street Parking Space	Access aisle not provided or not compliant Needs maintenance Not connected to accessible route Van-designated space not provided or not comp.		Priority 3	Approach & Entrance	Provide accessible parking spaces. Provide one van-accessible space. Provide marking at access aisle. Provide parking identification sign.	\$870.00			Park and Rec Director		
Weir Park	069		4. Off-street Parking Space	Not connected to accessible route		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Park	059		4. Off-street Parking Space	Sign not provided or not compliant		Priority 3	Approach & Entrance	Provide parking identification sign.	\$260.00			Park and Rec Director		
Weir Park	053		6. Gates	Gate smooth surface missing or not compliant Ground surface uneven, unstable or slippery		Priority 3	Approach & Entrance	Provide a smooth surface at gate.	\$100.00			Park and Rec Director		
Weir Park	061		6. Gates	Provide an accessible point of entry. Ground surface uneven, unstable or slippery Hardware not compliant Inadequate maneuvering clearances Needs maintenance		Priority 3	Approach & Entrance	Provide smooth surface at gate.	\$100.00			Park and Rec Director		
Weir Park	060		6. Gates	Gate smooth surface missing or not compliant Ground surface uneven, unstable or slippery Inadequate maneuvering clearances		Priority 3	Approach & Entrance	Provide sign to accessible point of entry.	\$260.00			Park and Rec Director		
Weir Park	066		6. Gates	Ground surface uneven, unstable or slippery		Priority 3	Priority 3	Provide an accessible route.	\$200.00			Park and Rec Director		
Weir Park	063		7. Lockers	B. Not on accessible route		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Park	065		2. Field	A. Not connected by accessible route C. Spectator seating not on accessible route E. Team seating not on accessible route F. Practice areas not on accessible route G. Needs maintenance		Priority 1	Program Access	Provide an accessible route to all amenities. Provide an accessible wheelchair space.	Dependent on distance			Park and Rec Director		
Weir Park	064		2. Field	C. Spectator seating not on accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	008		2. Curb Ramp	A. Not provided at Intersection G. Too narrow H. Uneven, unstable or slippery I. Changes in level / sidewalk transitions N. Needs maintenance		Priority 3	Approach & Entrance	Provide curb ramp.	\$1,635.00			Park and Rec Director		
Weir Riverfront Park	002		3. Sidewalk	B. Cross slope too steep C. Changes in level		Priority 3	Approach & Entrance	Correct cross slope at sidewalk.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	003		3. Sidewalk	D. Obstructed by grates C. Changes in level M. Needs maintenance		Priority 3	Approach & Entrance	Maintenance	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	021		4. Off-street Parking Space	Not connected to accessible route		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	023		4. Off-street Parking Space	Not provided		Priority 3	Approach & Entrance	Provide one van-accessible space. Provide marking at access aisle. Provide parking identification sign.	\$870.00			Park and Rec Director		
Weir Riverfront Park	001		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route H. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	016		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	017		1. Walkways	A. Surface uneven, unstable or slippery E. Running slope too steep F. Cross slope too steep M. Needs maintenance C. Route to all feature not provided		Priority 3	Approach & Entrance	Correct running and cross slopes.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	006		1. Walkways	A. Surface uneven, unstable or slippery G. Changes in level M. Needs maintenance		Priority 3	Approach & Entrance	Correct changes in level.	Dependent on distance			Park and Rec Director		

Weir Riverfront Park	009		2. Ramp	B. Too steep I. Needs maintenance		Priority 3	Approach & Entrance	Correct slope at ramp.	\$1,850.00			Park and Rec Director		
Weir Riverfront Park	014		1. Playground			Priority 1	Program Access					Park and Rec Director		
Weir Riverfront Park	011 a		1. Tables	C. Not connected by accessible route F. Needs maintenance		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	011 b		1. Tables	A. Total number of tables B. At least one or 5% not provided E. Knee clearance not provided F. Needs maintenance		Priority 4	Access to Goods and Services	Provide one accessible picnic table.	Dependent on distance			Park and Rec Director		
Weir Riverfront Park	024		3. Benches	A. Not connected by accessible route B. Ground surface uneven or slippery		Priority 4	Access to Goods and Services		Dependent on distance			Park and Rec Director		
Weir Riverfront Park	010		3. Benches	A. Not connected by accessible route B. Ground surface uneven or slippery C. Adjacent clear space not provided H. Needs maintenance		Priority 4	Access to Goods and Services	Provide one accessible route. Provide one wheelchair space.	Dependent on distance			Park and Rec Director		
Westside Park, Mulcahey	046		4. Off-street Parking Space	Access aisle not provided or not compliant Ground surface too steep [%] Not connected to accessible route Van-designated space not prov. or not comp.		Priority 3	Approach & Entrance	Provide one van-accessible space. Provide marking at access aisle. Provide parking identification sign.	\$870.00			Park and Rec Director		
Westside Park, Mulcahey	051		4. Off-street Parking Space	Access aisle not provided or not compliant Not connected to accessible route Total # of accessible parking spaces [quantity] Van-designated space not prov. or not comp.		Priority 3	Approach & Entrance	Provide one van-accessible space. Provide marking at access aisle. Provide parking identification sign.	\$870.00			Park and Rec Director		
Westside Park, Mulcahey	039		5. Point of Entry	C. Obstructed E. Uneven, unstable or slippery F. Not connected to accessible route		Priority 3	Approach & Entrance	Repair surface at point of entry.	\$300.00			Park and Rec Director		
Westside Park, Mulcahey	041		6. Gates	Gate smooth surface missing or not compliant Ground surface uneven, unstable or slippery Needs maintenance		Priority 3	Approach & Entrance	Provide smooth surface at gate.	\$100.00			Park and Rec Director		
Westside Park, Mulcahey	049		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided E. Running slope too steep F. Cross slope too steep G. Changes in level		Priority 3	Approach & Entrance	Correct running and cross slopes.	Dependent on distance			Park and Rec Director		
Westside Park, Mulcahey	047-048		1. Walkways	A. Surface uneven, unstable or slippery C. Route to all feature not provided F. Cross slope too steep G. Changes in level H. Water accumulation M. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Westside Park, Mulcahey	044		1. Walkways	A. Surface uneven, unstable or slippery M. Needs maintenance		Priority 3	Approach & Entrance		\$300.00			Park and Rec Director		
Westside Park, Mulcahey	040		2. Field	A. Not connected by accessible route E. Team seating not on accessible route F. Practice areas not on accessible route		Priority 1	Program Access	Provide an accessible route to all amenities.	Dependent on distance			Park and Rec Director		
Whittenton Park	039		5. Point of Entry	E. Uneven, unstable or slippery		Priority 3	Approach & Entrance		\$300.00			Park and Rec Director		
Whittenton Park	037		3. Sidewalk			Priority 3	Approach & Entrance		Dependent on distance			Park and Rec Director		
Whittenton Park	038		4. Off-street Parking Space	Access aisle not provided or not compliant Ground surface too steep [%] Needs maintenance Not connected to accessible route Sign not provided or not compliant Van-designated space not prov. or not comp.		Priority 3	Approach & Entrance	Provide one van-accessible space. Provide marking at access aisle. Provide parking identification sign.	\$870.00			Park and Rec Director		
Whittenton Park	031		5. Point of Entry	E. Uneven, unstable or slippery F. Not connected to accessible route H. Needs maintenance		Priority 3	Approach & Entrance	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Whittenton Park	033		1. Playgrounds	A. Not connected by accessible route.		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Whittenton Park	035		1. Court	A. Not connected by accessible route		Priority 1	Program Access	Provide an accessible route.	Dependent on distance			Park and Rec Director		
Whittenton Park	032		3. Benches	A. Not connected by accessible route.		Priority 4	Access to Goods and Services	Provide an accessible route.	Dependent on distance			Park and Rec Director		
TOTAL **									\$41,029.60					